

TOWN FOOD SERVICE EQ

SMOKEHOUSE WITH FRONT PANEL REMOVED

THERMOCOUPLE CONNECTION. MAKE SURE THIS IS TIGHT AND CORROSION FREE. "TIGHT" MEANS THAT THE NUT SHOULD BE TIGHTENED BY HAND, THEN AN ADDITIONAL 1/4" TURN USING AN OPEN ENDED WRENCH

THERMOCOUPLE LINE. FOLLOW THIS TO ACTUAL THERMOCOUPLE INSIDE UNIT (249006)

SAFETY PILOT VALVE (249011 - ENTIRE VALVE) (249011H - REPAIR KIT)

THERMOSTAT (249007)

GAS VALVE (226102F)

PILOT BURNER GAS HOSE (226224)

TEST TAP. SHOULD MEASURE 6" W.C. FOR NATURAL GAS UNITS OR 10" W.C. FOR PROPANE GAS UNITS

GAS PRESSURE REGULATOR (249047).

IF THINGS ARE PARTICULARLY MESSY, THE PILOT MIGHT BE CLOGGED. CLEAN ORIFICE OR REPLACE WITH NEW PILOT BURNER (249012 FOR NATURAL GAS AND 249009 FOR LP GAS)

PILOT FLAME ADJUSTMENT SCREW. CAP MUST BE REMOVED TO REVEAL ADJ. SCREW. YOU MUST REINSTALL THE CAP TO PREVENT GAS LEAKS. PILOT FLAME MUST FULLY ENVELOPE THE THERMOCOUPLE.

GAS INLET. PRESSURE CAN'T EXCEED 15" WATER COLUMN. IF CONNECTED TO A PROPANE TANK OR A 1-2 PSI GAS SYSTEM, A FIRST STAGE REGULATOR IS REQUIRED. TO BE SUPPLIED BY OTHERS.